

From PVC pipe to a christmas tree

PVC pipe 30min at 250 degrees celcius in the oven.

Cut through the entire tube

make a right. For example, heavy things on them.

all let it cool down

Oven at 150 degrees and put it back celcius in the oven

To 5minuten Remove and cut a piece.

After 2minuten paved the weather and must often return.

It takes around 2 hours



Thinks to need:

- PVC pipe
- Oven
- Knife
- Scissors

